Visit: www.thesafetyequipmentstore.com Or Email: besafe@thesafetyequipmentstore.com for Sales & Service. 178 | DrägerSensor® XS

# DrägerSensor<sup>®</sup> XS EC O<sub>2</sub>-LS DrägerSensor<sup>®</sup> XS 2 O<sub>2</sub> DrägerSensor<sup>®</sup> XS R O<sub>2</sub>

Order no.	68	09	130
	68	10	375
	68	10	262

Used in	Plug & Play	Replaceable	Guaranty*	Expected sensor life	Selective filter
Dräger X-am 7000	yes	yes	XS EC: 3 years	> 5 years	-
			XS 2: 2 years	> 3 years	
			XS R: 5 years	= 5 years	
				(limited operation	on time)

#### MARKET SEGMENTS

Sewage, mining and tunneling, fumigation, biogas, measuring hazmat, industrial gases.

### **TECHNICAL SPECIFICATIONS**

Detection limit:	0.1 Vol. %	
Resolution:	0.1 Vol. %	
Measurement range:	0 to 25 Vol. % O <sub>2</sub> (oxygen)	
Response time:	≤ 25 seconds (T <sub>90</sub> ) – XS EC	
	$\leq$ 20 seconds (T <sub>90</sub> ) – XS 2 / XS R	
Measurement accuracy		
Sensitivity:	$\leq \pm 1\%$ of measured value	
Long-term drift, at 20°C (68°F)		
Zero point:	≤ ± 0.5 Vol. %/year	
Sensitivity:	$\leq \pm 1\%$ of measured value/month	
Warm-up time:	≤ 1 hour	
Ambient conditions		
Temperature:	(-40 to 50)°C (-40 to 122)°F	
Humidity:	(10 to 90)% RH	
Pressure:	(700 to 1,300) hPa	
Influence of temperature		
Zero point:	≤ ± 0.4 Vol. % XS EC	
	≤ ± 0.2 Vol. % XS 2 / XS R	
Sensitivity:	$\leq \pm 2\%$ of measured value XS EC	
	$\leq$ ± 1% of measured value XS R / XS 2	
Influence of humidity		
Zero point:	≤ ± 0.002 Vol. %/% RH – XS EC	
	No effect – XS 2 / XS R	
Sensitivity:	≤ ± 0.1% of measured value/% RH	
Test gas:	N <sub>2</sub> (zero gas)	
	11.5 to 23.0 Vol. % O <sub>2</sub>	

| 179

#### SPECIAL CHARACTERISTICS

DrägerSensor® XS oxygen sensors are lead-free, thus complying with Directive 2002/95/EC (RoHS). Because they are non-consuming sensors, they have a much longer life spans than sensors that are consuming.

The values shown in the following table are standard and apply to new sensors. The values maybe fluctuate by  $\pm$  30%. The sensor may also be sensitive to additional gases (for more information, please contact Dräger). Gas mixtures may be displayed as the sum of all components. Gases with a negative cross sensitivity may displace an existing concentration of O<sub>2</sub>. To be sure, please check if gas mixtures are present.

### RELEVANT CROSS-SENSITIVITIES DrägerSensor® XS EC O<sub>2</sub> LS

Gas/vapor	Chem. symbol	Concentration	Display in Vol. % O <sub>2</sub>
Chlorine	Cl <sub>2</sub>	20 ppm	No effect
Carbon dioxide	CO <sub>2</sub>	5 Vol. %	No effect
Carbon monoxide	CO	0.5 Vol. %	≤ 0.3(-)
Ethane	C <sub>2</sub> H <sub>6</sub>	5 Vol. %	No effect
Ethanol	C <sub>2</sub> H <sub>5</sub> OH	1 Vol. %	≤ 0.2(-)
Ethene	C <sub>2</sub> H <sub>4</sub>	2 Vol. %	≤ 0.5(-)
Ethine	C <sub>2</sub> H <sub>2</sub>	0.5 Vol. %	≤ 0.2 <sup>(-)</sup>
Hydrogen	H <sub>2</sub>	1 Vol. %	≤ 1.6(-)
Hydrogen chloride	HCI	40 ppm	No effect
Hydrogen sulfide	H <sub>2</sub> S	100 ppm	No effect
Methane	CH <sub>4</sub>	10 Vol. %	No effect
Nitrogen dioxide	NO <sub>2</sub>	50 ppm	No effect
Nitrogen monoxide	NO	100 ppm	No effect
Propane	C <sub>3</sub> H <sub>8</sub>	2 Vol. %	No effect
Sulfur dioxide	SO <sub>2</sub>	50 ppm	No effect

# Visit: www.thesafetyequipmentstore.com Or Email: besafe@thesafetyequipmentstore.com for Sales & Service.

180 | DrägerSensor® XS

## RELEVANT CROSS-SENSITIVITIES DrägerSensor® XS 2 O2

Gas/vapor	Chem. symbol	Concentration	Display in Vol. % O <sub>2</sub>
Chlorine	Cl <sub>2</sub>	20 ppm	No effect
Carbon dioxide	CO <sub>2</sub>	5 Vol. %	No effect
Carbon monoxide	CO	0.5 Vol. %	≤ 0.3(-)
Ethane	C <sub>2</sub> H <sub>6</sub>	5 Vol. %	No effect
Ethanol	C <sub>2</sub> H <sub>5</sub> OH	1 Vol. %	≤ 0.2(-)
Ethene	C <sub>2</sub> H <sub>4</sub>	2 Vol. %	≤ 0.5 <sup>(-)</sup>
Ethyne	$C_2H_2$	0.5 Vol. %	≤ 0.2(-)
Hydrogen	H <sub>2</sub>	1 Vol. %	≤ 1.6 <sup>(-)</sup>
Hydrogen chloride	HCI	40 ppm	No effect
Hydrogen sulfide	H <sub>2</sub> S	100 ppm	No effect
Methane	CH <sub>4</sub>	10 Vol. %	No effect
Nitrogen dioxide	NO <sub>2</sub>	50 ppm	No effect
Nitrogen monoxide	NO	100 ppm	No effect
Propane	C <sub>3</sub> H <sub>8</sub>	2 Vol. %	No effect
Sulfur dioxide	SO <sub>2</sub>	50 ppm	No effect

# RELEVANT CROSS-SENSITIVITIES DrägerSensor® XS R O2

Gas/vapor	Chem. symbol	Concentration	Display in Vol. % O <sub>2</sub>
Chlorine	Cl <sub>2</sub>	20 ppm	No effect
Carbon dioxide	CO <sub>2</sub>	5 Vol. %	No effect
Carbon monoxide	CO	0.5 Vol. %	≤ 0.3 <sup>(-)</sup>
Ethane	C <sub>2</sub> H <sub>6</sub>	5 Vol. %	No effect
Ethanol	C <sub>2</sub> H <sub>5</sub> OH	1 Vol. %	≤ 0.2(-)
Ethene	C <sub>2</sub> H <sub>4</sub>	2 Vol. %	≤ 0.5 <sup>(-)</sup>
Ethyne	$C_2H_2$	0.5 Vol. %	≤ 0.2(-)
Hydrogen chloride	HCI	40 ppm	No effect
Hydrogen sulfide	H <sub>2</sub> S	100 ppm	No effect
Methane	CH <sub>4</sub>	10 Vol. %	No effect
Nitrogen dioxide	NO <sub>2</sub>	50 ppm	No effect
Nitrogen monoxide	NO	100 ppm	No effect
Propane	C <sub>3</sub> H <sub>8</sub>	2 Vol. %	No effect
Sulfur dioxide	SO <sub>2</sub>	50 ppm	No effect

Visit: www.thesafetyequipmentstore.com Or Email: besafe@thesafetyequipmentstore.com for Sales & Service.

| 181



DrägerSensor® XS O<sub>2</sub>